

Inspection Report Detail

Multiple dates are available for this VIN. Please choose one:

12-12-2008 ▾

Inspection Summary

Ally Account #:

Customer Name:

Co-Customer:

Inspection Company: Autovin

Inspector ID: 183984

Return Date: 01-26-2008

Inspection Date: 10-06-2008

Condition Grade: 1

Comments: TEST.

Vehicle Information & Photos

VIN: 137PH84336E232861

Year: 2006

Interior Color: Green

Mileage: 3698

Make: Hummer

Exterior Color: Dark Blue

License State/Plate:

Model: H1

Smoker: Yes

Series: N/A Hardtop

None

[Back to top](#)

Dealer Information

Dealer Number: 82235001

Dealer Name: ADESA CALGARY

Contact Name:

Dealer Address: Box 5280 Irricana Rd NE, Airdrie, AB T4B 2T9

Telephone:

[Back to top](#)

Damage Information & Photos

[View Ally Excess Wear Table: US | Canada \(PDF 46K\)](#)

Chargeable Wear: \$3,597.38

Non-Chargeable Wear: \$100.00

Total Wear: \$3,697.38

Exterior Damage:

| Location | Description | Chargeable | Frame Hrs | Paint Hrs | Metal Hrs | Repair Hrs | Part Cost | Total Cost | Image |
|---------------------------|---------------------------------|------------|-----------|-----------|-----------|------------|-----------|------------|-------|
| FENDER PANEL Fender | Dent(s)/ Non-Chargeable | Yes | | 2.6 | 1.0 | | | \$180.00 | |
| FENDER PANEL Fender | Dent(s)/ No Paint Damage/ PDR | No | | | | | \$50.00 | \$50.00 | |
| Front Bumper FRONT BUMPER | Painted Signs Repaint | Yes | | 2.6 | | | | \$130.00 | |
| Hood HOOD PANEL | Dent(s)/ No Paint Damage/ PDR | No | | | | | \$50.00 | \$50.00 | |
| Rear Bumper BUMPER | Gouge(s) Repair (Entire Bumper) | Yes | | | | | \$200.00 | \$200.00 | |
| RF Door Panel DOOR PANEL | Dent(s)/ Severe | Yes | | 2.3 | | 7.5 | \$313.69 | \$803.69 | |

Interior Damage:

| Location | Description | Chargeable | Frame Hrs | Paint Hrs | Metal Hrs | Repair Hrs | Part Cost | Total Cost | Image |
|--------------------------------|---|------------|-----------|-----------|-----------|------------|------------|------------|-------|
| 3rd Seat Folding Seat Module | Missing Replace | Yes | | | | | \$2,000.00 | \$2,000.00 | |
| LF Interior Door INTERIOR TRIM | Broken/ Replace | Yes | | | | | \$33.15 | \$33.15 | |
| LR Door Interior INTERIOR TRIM | Broken/ Replace | Yes | | | | | \$25.54 | \$25.54 | |
| Wipers/Washer Motor | Inoperable The wiper motor is not functioning. Le | No | | | | | | | |

Other Damage/Charges:

| Location | Description | Chargeable | Frame Hrs | Paint Hrs | Metal Hrs | Repair Hrs | Part Cost | Total Cost | Image |
|------------------------------|-------------|------------|-----------|-----------|-----------|------------|-----------|------------|-------|
| ADD FOR Fender | Refinish | Yes | | | | 0.5 | | \$25.00 | |
| Left Frame/ Cosmetic ADD FOR | Refinish | Yes | | | | 0.5 | | \$25.00 | |

[Back to top](#)

Tire Information & Photos:

| Tire | Manufacturer | Tire Size | Tread Depth | Description | Tire Cost | Image |
|-------------|--------------|-----------|-------------|---------------------------|-----------|-------|
| Front-Left | Amstrong | 17 | 10mm | Plugged Sidewall/ Replace | \$175.00 | |
| Front-Right | Amstrong | 17 | 10mm | | \$0.00 | |
| Rear-Left | Commander | 17 | 10mm | | \$0.00 | |
| Rear-Right | Amstrong | 17 | 10mm | | \$0.00 | |
| Spare | Amstrong | 17 | 10mm | | \$0.00 | |

[Back to top](#)

Verified Options & Accessories

Interior: _____ Exterior: _____ Mechanical: _____ Other: _____

After Market (AM): _____

[Back to top](#)